

PW MILLAR LTD

ESTABLISHED 1970

2018-68 | LAND ROVER DISCOVERY

SPORT

2.0 TD4 HSE 4WD Euro 6 (s/s) 5dr, 7 Seats | Diesel | Manual | Firenze Red



<https://www.pwmillar.co.uk>
01446 733248



£9,490

From **£247** per month HP

Mileage	54,983 miles
Fuel	Diesel
Owners	1
Engine	2 litre
Transmission	Manual
Gears	6
Insurance group	29E

SPECIFICATIONS

Emergency brake assist	Cruise control + speed limiter	Body colour door handles
Cirrus morzine headlining	Dynamic stability control	Centre stack side rails in satin brushed aluminium
Immobiliser	CD/DVD player	19" 5 Split spoke alloy wheels - Style 521
Hill start assist	Rear view camera	Body colour mirror caps
Third row dual adjustable individual seats	Diesel particulate filter	Locking wheel nuts
Bluetooth connectivity including audio streaming	Tyre repair kit	ESP + traction control
Lane departure warning system	Solid paint	Isofix child seat preparation
Terrain Response	Intrusion sensor	Steering wheel mounted audio controls
ABS	PAS	Heated windscreen
Twin cupholders in rear centre armrest	Remote central locking	DAB Digital radio
Tyre pressure monitoring system	8" colour display screen	Electric adjustable/heated/folding door mirrors with approach lights
2nd row 60/40 split/fold	Perimeter alarm with volume sensing	USB connection located in centre console
Side and curtain airbags for front and 2nd row seats	Electric gesture tailgate/boot lid	Auto dimming interior mirror
Leather steering wheel	Keyless entry	InControl protect

TECHNICAL

Performance	
0-100 kmh (62 mph)	10.3 s
Top speed	117 mph
Emissions Ice	
CO ₂ (g/km)	170 (g/km)
Fuel Consumption Ice	
MPG (combined)	36.7 mpg
L/100km (combined)	7.7 l/100km
MPG (combined)	44.1 mpg
MPG (extra urban)	61.4 mpg
MPG (urban)	44.1 mpg
Capacities	
Boot (seats up)	981 litres
Boot (seats down)	1698 litres
Fuel tank	54 litres
General	
NCAP Overall	5

....MORE.... For the full details please call us or scan the QR code above

01446 733248

sales@pwmillar.co.uk

P W Millar 148 Port Road East Barry South Glamorgan CF62 9PZ

Whilst every effort has been made to ensure the accuracy of the vehicle specification, some inaccuracies may occasionally occur. It is important that you do not rely solely on this information, but check with a member of the sales staff about any features which may affect your decision to buy the car.